



Photograph 46:
View north on Old Broadway from middle of Block 1986



Photograph 45:
View east on West 131st Street
from western end of Block 1998

Manhattanville Neighborhood Conditions Study



Photograph 47: View north of Twelfth Avenue from western end of Block 1998



Photograph 48: View east on West 132nd Street from western end of Block 1998

Manhattanville Neighborhood Conditions Study



Photograph 49: View east on West 131st from Block 1997 Lot 55



Photograph 50: View east on West 130th Street from Block 1997 Lot 14

Manhattanville Neighborhood Conditions Study



Photograph 51: View west on West 130th Street from middle of Block 1997



Photograph 52: View west on West 130th Street from Block 1996 Lot 56


Manhattanville Neighborhood Conditions Study



Photograph 53: View northwest from Broadway and West 125th Street



Photograph 54: View southeast from eastern end of Block 1999



Photograph 55:
View under Manhattan Valley IRT
Viaduct from West 125th Street



Photograph 56: View southwest from western end of Block 1986

Manhattanville Neighborhood Conditions Study



Photograph 57: View northwest on West 125th Street from eastern end of Block 1996 Lot 1



Photograph 58: View north from West 125th Street and Twelfth Avenue

Manhattanville Neighborhood Conditions Study



Photograph 59: View south through study area from eastern end of Block 1998